

## PROJECT NAME

Strut Assembly Redesign

Analyze the types of failures and the root causes of Marposs measuring stations for tappets determination.

Introducerea analiza cauzei radacina in aplicatia QLS (quality leadership system) pentru problemele gasite la testul Squeak & Rattle (zgomote in rulaj), de catre personalul din zona de reparatii

Optimizare flux masini in zona test area vehicule (One Drive, Engineering Specification-test, Airleak test, Static water test, Wheel alignment)

Panou afisare in sistem informatic ajutoare vizuale, suport pentru inspectiile de calitate

Imbunatatire sistem inspectii ISPC (in statia de lucru) versus Inspectii CAL ( customer acceptance line) minim 20 defecte, 100% actiuni corective in linia de fabricatie

FACULTY	TOTAL PROJECTS IDENTIFIED
Electrical Faculty	6